

COGCC Inspection Photos.

API # 077-09712

Inspection # 696600499




Photo #1. Sign is posted at the entrance to location.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo #2 Photo at entrance to location



Photo #3 Photo at entrance to location

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 4. Photo of Tank Battery



Photo #5. Photo of Wellheads.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo#6. Holes inside of containment liner.



Photo#7. Holes inside of containment liner.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo # 8. Holes inside of containment liner.



Photo # 9. Holes inside of containment liner.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 10. Stained soil or gravel be the separators.



Photo# 11. Stained soil or gravel be the separators.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 12. Trash left on location



Photo #13 Trash left on location

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 14. Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment moving off slope and choking out vegetation.



Photo# 15. Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment moving off slope and choking out vegetation.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 16 Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment moving off the slope and choking out vegetation.



Photo# 17. Erosion is evident along un-stabilized slope on the South side of location. Erosion sediment moving off the slope and choking out vegetation.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 18. Drain pipe is being used as a BMP and is in need of maintenance.



Photo# 19. Drain pipe is being used as a BMP and is in need of maintenance.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo# 20. Lined ditch on the West side of location, is being used as a BMP and is in need of maintenance.



Photo# 21 Lined ditch on West the side of location, is being used as a BMP and is in need of maintenance.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo #22. Erosion sediment is moving off un-stabilized berm on the west side of location below the berm, and is choking out vegetation



Photo #23. . Erosion sediment is moving off un-stabilized berm on the west side of location below the berm, and is choking out vegetation

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



Photo #24. South/East has become un-stabilized and erosion is moving soil down the hill. Vegetation is being choke out. BMP needs maintenance.



Photo #25. South/East has become un-stabilized and erosion is moving soil down the hill. Vegetation is being choke out. BMP needs maintenance.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



photo #26. On top of the South/East slope, erosion sediment is moving down the slope and is choking out sediment.



photo #27. On top of the South/East slope, erosion sediment is moving down the slope and is choking out sediment.

COGCC Inspection Photos.
API # 077-09712
Inspection # 696600499



photo #28. South/East has become un-stabilized and erosion is moving soil down the hill. Vegetation is being choke out. BMP needs maintenance.



photo #29. South/East has become un-stabilized and erosion is moving soil down the hill. Vegetation is being choke out. BMP needs maintenance.