

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2019

Submitted Date:

08/16/2019

Document Number:

694900218**FIELD INSPECTION FORM**

Loc ID 335132 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:25 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285851	WELL	PR	04/24/2007	GW	045-12575	CLOUGH RWF 522-23	PR
285852	WELL	PR	09/30/2008	GW	045-12574	CLOUGH RWF 412-23	PR
285853	WELL	PR	09/30/2008	GW	045-12573	CLOUGH RWF 422-23	PR
285854	WELL	PR	04/24/2007	GW	045-12572	CLOUGH RWF 11-23	PR
285855	WELL	PR	08/31/2008	GW	045-12571	CLOUGH RWF 22-23	PR
285856	WELL	PR	08/31/2008	GW	045-12570	CLOUGH RWF 411-23	PR
285857	WELL	PR	10/31/2008	GW	045-12569	CLOUGH RWF 312-23	PR
285858	WELL	PR	04/24/2007	GW	045-12568	CLOUGH RWF 21-23	PR
285859	WELL	PR	04/24/2007	GW	045-12567	CLOUGH RWF 321-23	PR
285860	WELL	PR	04/24/2007	GW	045-12566	CLOUGH RWF 421-23	PR
285861	WELL	PR	09/30/2008	GW	045-12565	CLOUGH RWF 512-23	PR
285862	WELL	PR	09/30/2008	GW	045-12564	CLOUGH RWF 12-23	PR
285863	WELL	PR	06/15/2008	GW	045-12563	CLOUGH RWF 311-23	PR
294707	WELL	PR	08/12/2008	GW	045-15575	CLOUGH RWF 544-15	PR
294708	WELL	PR	02/26/2008	GW	045-15576	CLOUGH RWF 156-15	PR

General Comment:

Follow-up inspection from FIR DOC # 689303500. Corrective actions have been completed.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	centralized battery				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate	Walls Sufficient		Base Sufficient		Adequate
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment: centralized battery						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate	Walls Sufficient		Base Sufficient		Adequate
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	200 BBLs	STEEL AST		,	
Comment: centralized battery						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate	Walls Sufficient		Base Sufficient		Adequate
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment: centralized battery						
Corrective Action:						Date:
<u>Paint</u>						

Inspector Name: Ramsey, Scott

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	285851	Type:	WELL	API Number:	045-12575	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285852	Type:	WELL	API Number:	045-12574	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285853	Type:	WELL	API Number:	045-12573	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285854	Type:	WELL	API Number:	045-12572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285855	Type:	WELL	API Number:	045-12571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285856	Type:	WELL	API Number:	045-12570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285857	Type:	WELL	API Number:	045-12569	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	285858	Type:	WELL	API Number:	045-12568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			

Facility ID: 285859	Type: WELL	API Number: 045-12567	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 285860	Type: WELL	API Number: 045-12566	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 285861	Type: WELL	API Number: 045-12565	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 285862	Type: WELL	API Number: 045-12564	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 285863	Type: WELL	API Number: 045-12563	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 294707	Type: WELL	API Number: 045-15575	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 294708	Type: WELL	API Number: 045-15576	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary On Friday 8/16/19 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a Follow up inspection at TEP Clough 421-23 Pad, at Location # 335132 in Garfield County, Colorado. While there, I observed Normal production operations. All C/A(s) have been completed. This is a summary of inspection report.	ramseys	08/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900225	694900218	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912196