

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2019

Submitted Date:

08/16/2019

Document Number:

694900221**FIELD INSPECTION FORM**

Loc ID 335159 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288866	WELL	PR	07/17/2007	GW	045-13602	CLOUGH RWF 324-14	PR
288867	WELL	PR	01/10/2007	GW	045-13601	CLOUGH RWF 24-14	PR
288868	WELL	PR	01/10/2007	GW	045-13600	CLOUGH RWF 14-14	PR
288869	WELL	PR	01/10/2007	GW	045-13599	CLOUGH RWF 314-14	PR
288870	WELL	PR	01/10/2007	GW	045-13598	CLOUGH RWF 414-14	PR

**General Comment:**

follow up inspection for DOC # 689302054 Corrective actions have been completed.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 5		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	centralized containment				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	centralized containment				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288866	Type:	WELL	API Number:	045-13602	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	288867	Type:	WELL	API Number:	045-13601	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	288868	Type:	WELL	API Number:	045-13600	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	288869	Type:	WELL	API Number:	045-13599	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	288870	Type:	WELL	API Number:	045-13598	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Gravel				
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Friday 8/16/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at TEP Clough RWF 314-14 Pad, at Location # 335159 in Garfield County, Colorado.  While there, I observed Normal production operations. All C/A(s) have been completed.  This is a summary of inspection report.</p>	ramseys	08/16/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900226	694900221	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912199">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4912199</a>