

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2019

Submitted Date:

08/09/2019

Document Number:

679705029

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
430928 \_\_\_\_\_ Moran, Rick \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10591  
Name of Operator: AUGUSTUS ENERGY PARTNERS II LLC  
Address: 2016 GRAND AVENUE SUITE A  
City: BILLINGS State: MT Zip: 59102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 14 Number of Comments  
6 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Zimmerman, Duane	406-860-1432	dzimmerman@augustusenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430928	WELL	PR	12/05/2014	OW	103-11954	Wiley 23-3-97 H1	PR
442990	WELL	AL	04/15/2019	LO	103-12277	BHR Fee O23-26-397-2RH	AL

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 8-9-2019 at approximately 13:00, inspector Rick Moran, conducted a routine inspection at Augustus Energy Partners II well Wiley 23-3-97 H1 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Oily rags in open bucket. Photo 2. Complete by 9-9-2019.
- 2) Stained soil next to separator & tanks. Photos 3, 4, 5, 6. Complete by 9-9-2019.
- 3) Detached well head sign. Photo 7. Complete by 10-9-2019.
- 4) 3 tanks missing labels. Photos 8 & 9. Complete by 10-9-2019.
- 5) 3 barrels without labels. Photos 10, 11, 12. Complete by 10-9-2019.
- 6) Missing bird protection on stack west side of 500 bbl tanks. Photo 13. Complete by 9-9-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705029.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	3 barrels without labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/09/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head sign lying on ground upside down.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/09/2019
Type	TANK LABELS/PLACARDS		
Comment:	500 bbl tank missing NFPA label & contents. 2 tanks next to separator without labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/09/2019

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil next to separator with absorbent pads on top. Stained gravel next to tank burners & oil valve.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/09/2019
Type	STORAGE OF SUPL		
Comment:	Oily rags stored in open bucket next to 500 bbl tanks.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/09/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		

Comment:		
Corrective Action:		Date:
Type	SEPARATOR	
Comment:		
Corrective Action:		Date:

<b>Equipment:</b>		corrective date
Type: Bird Protectors	# 11	
Comment:	One stack on west side of 500 bbl tank battery without bird protection.	
Corrective Action:	Install wildlife screen per Rule 605.b.(7).	Date: 09/09/2019
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 9	
Comment:	2 containers of methanol, 1 container glycol, 1 container motor oil, 2 Costalguard EG 50, and 3 containers of unknown contents.	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		40.209900,-108.241400
Comment:	Tank without label.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<100 BBLs	FIBERGLASS AST		40.209900,-108.241400
Comment:	Tank without label.				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		40.209300,-108.241000
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	500 BBLs	STEEL AST		40.209300,-108.241000
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 430928 Type: WELL API Number: 103-11954 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action:

Date:

Facility ID: 442990 Type: WELL API Number: 103-12277 Status: AL Insp. Status: AL

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: No visual surface evidence of well.

Abandon permit Form 4 document 402008150 dated 4-15-2019.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass			Material Handling And Spill Prevention	Pass	
Check Dams	Pass					
Retention Ponds	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402140314	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905593">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905593</a>
679705030	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905590">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905590</a>