

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2019

Submitted Date:

08/11/2019

Document Number:

696600465**FIELD INSPECTION FORM**
 Loc ID 312622 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222050	WELL	SI	03/01/2019	GW	077-08652	HORSESHOE CANYON 1-19	SI

General Comment:[Routine FIU General Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		,
Comment:	62 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222050	Type:	WELL	API Number:	077-08652	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:									
Corrective Action:								Date:	
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		Shut in 1/19 is the last production shown.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
		Gravel	Fail			
Gravel	Pass					
Compaction	Pass					
		Sediment Traps	Fail			
		Check Dams	Fail			

Comment: Stormwater erosion not being controlled on the access road at this time. BMP's not in place or need maintenance.
Erosion sediment moving down access road and onto location. No BMP's in place or in need of maintenance. See photos 6-9

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 09/09/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Friday) (8/9/19) at approximately (1405) I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Horseshoe Canyon 1-19), (API #077-08652) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Stormwater issues were observed: Stormwater on access road is in need of maintenance. BMP's not in place or need maintenance. Erosion sediment moving down access road and onto location. No BMP's in place or in need of maintenance. See photos 6-9. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402140373	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905654
696600466	Inspection 696600465 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905646