

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/19/2019

Document Number:

687905394

FIELD INSPECTION FORM

Loc ID 334132 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 19 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215818	WELL	PR	03/24/1994	GW	067-07423	SIMON LAND & CATTLE 15U-2R 1	PR
286249	WELL	PR	07/10/2007	GW	067-09230	SIMON LAND & CATTLE 15U-2R 3	PR
286250	WELL	PR	07/24/2007	GW	067-09229	SIMON LAND & CATTLE 15U-2R 4	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign and on tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Date: _____
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	SEPARATOR		
Comment:	Cattle panels around separators, meter houses and produced water tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels around wellheads, LRP's and pumpjack.		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 3		corrective date
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:	(2) LRP's (1) pumpjack.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	(1) on duell separator stack and (1) on single separator stack.		
Corrective Action:		Date:	
Type: Flow Line	# 15		

Comment:	3-3" flowlines from wellheads to separators. 3-2" flowlines from separator blowdown to produced water tank. 3-2" flowlines from separator dump valves to produced water tank and to offsite produced water gathering system. 3-3" flowlines from separators to meter houses. 3-3" flowlines from meter houses to offsite doglegs.		Date:
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Wellheads.		
Corrective Action:			Date:
Type: Prime Mover	# 3		
Comment:	Electric VFD drive motors (2) on LRP's and (1) on pumpjack with MCC.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:	(1) dual separator unit and (1) single separator unit.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 215818 Type: WELL API Number: 067-07423 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 286249 Type: WELL API Number: 067-09230 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 286250 Type: WELL API Number: 067-09229 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gravel	Pass					
Gradient Terraces	Pass	Gravel	Pass			
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905398	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913069