

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

696500352**FIELD INSPECTION FORM**
 Loc ID 328416 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248167	WELL	PA	04/06/2015	GW	123-15965	EHRlich 23-11	PA
426467	WELL	PR	08/01/2018	OW	123-34700	EHRlich PC O 23-67HN	PR
426468	WELL	PR	11/15/2012	OW	123-34701	EHRlich PC O 23-69HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol systems		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 2		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel and pipe fencing		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		

Comment:		Pilots are on		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 7				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 11				
Comment:		Three automation arrays, five ECD scrubbers, two methanol systems and one solar array.		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Pig Station	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:		Bradenhead valves are exposed at surface.		Date:	
Corrective Action:				Date:	
Type: VRU	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspector Name: Peterson, Tom

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	3	<100 BBLS	BV CONCRETE		,		
Comment:		60 bbls					
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	5	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:

Yes/No	NO						
Comment:							
Corrective Action:						Date:	

Flaring:

Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 248167 Type: WELL API Number: 123-15965 Status: PA Insp. Status: PAFacility ID: 426467 Type: WELL API Number: 123-34700 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 426468 Type: WELL API Number: 123-34701 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696500353	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913606