

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

694900228

FIELD INSPECTION FORM

Loc ID 335280 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		scollett@vnreenergy.com	
, vanguard		sghan@vnreenergy.com	SR. EH&S
, vanguard		aaxelson@vnreenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211380	WELL	PR	04/20/1997	GW	045-07140	GIBSON GULCH UNIT 8-30	PR
267918	WELL	PR	08/03/2003	GW	045-09221	GIBSON GULCH 8-30B	PR
267919	WELL	PR	08/03/2003	GW	045-09222	GIBSON GULCH 8-30 C	PR
463559	OFF-LOCATION FLOWLINE	AC	03/27/2019		-	Wellhead Line 30SENE	AC

General Comment:

[Follow up inspection from FIRR # 401820208](#)

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type TANK BATTERY

Comment: livestock fence

Corrective Action:

Date:

Type SEPARATOR

Comment: livestock fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Horizontal Heated Separator

4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Bird Protectors

7

Comment:

Corrective Action:

Date:

Type: Plunger Lift

4

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	YES			
Comment:	braden heads open			
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	<u>211380</u>	Type:	<u>WELL</u>	API Number:	<u>045-07140</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>267918</u>	Type:	<u>WELL</u>	API Number:	<u>045-09221</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>267919</u>	Type:	<u>WELL</u>	API Number:	<u>045-09222</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>463559</u>	Type:	<u>OFF-</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/19/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Vanguard GGO 8-30, at Location # 335280 in Garfield County, Colorado. While there, I observed Normal production operations. All C/A (s) have been completed. This is a summary of inspection report.</p>	ramseys	08/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900229	694900228	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913703