

Inspection Photos
Location Name:UPRR Pan AM F 1
Location ID:317660



Photo #1 Weeds growing on access road



Photo #@ WH Sign

Inspection Photos
Location Name:UPRR Pan AM F 1
Location ID:317660



Photo #3 Pump jack

Photo #4 debris around pump jack and electric motor