

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

699300013**FIELD INSPECTION FORM**
 Loc ID 317651 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239692	WELL	PR	03/20/1995	GW	123-07480	SUCKLA-BROWN UNIT 1	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign faded becoming not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/19/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue, 1" valve on tubing flowline appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/19/2019
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	"Properly treat or dispose of oily waste in accordance with 907.e."		Date: 09/19/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	electrical panel		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	apperars to be plumbed to surface		

Inspected Facilities

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 8/19/19 at approximately 10:00 am, I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #1 KP Kauffman, API # 123-07480 in (WeldCounty) Colorado.</p> <p>While there, I observed a producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil: Rule 907.e Corrective action date 9/19/2019 See attached photo # 3</p> <p>Sign faded: Rule 210.e Corrective action date 9/19/19 See attached photo #1</p> <p>Mechanical issue: Rule 605.d Corrective action Date 9/19/19 See attached photo # 3</p> <p>At time of inspection I observed stained soil around WH what appeared to be a leaking 1" valve on flow line. Well Head sign is fading and will need to be replaced.</p> <p>Weather conditions Sunny and clear Location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>This is a continuing education inspection.</p>	revasr	08/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300014	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913755