

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

699300015**FIELD INSPECTION FORM**
 Loc ID 318307 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241085	WELL	PR	09/08/1976	OW	123-08873	SUCKLA-BROWN UNIT 12	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing on access road see photo #1		
Corrective Action	Comply with Rule 603.f .		Date: 09/02/2019
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign fading and becoming unlegible see photo #2		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/19/2019
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue 1" valve on tubind appears to be leaking		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e."		Date: 09/19/2019
Type	TRASH		
Comment:	Trash on location by electric panel see photo #4		
Corrective Action:	Comply with Rule 603.f .		Date: 09/02/2019
Type	OTHER		
Comment:	Stained soil around WH see photo #5		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e."		Date: 09/19/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	steel tubing		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	electrical panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241085 Type: WELL API Number: 123-08873 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 8/19/19 at approximately 11:30 am, I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #12 KP Kauffman, API # 123-08873 in (WeldCounty) Colorado.</p> <p>While there, I observed a producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil: Rule 907.e Corrective action date 9/19/2019 See attached photo # 5</p> <p>Sign faded: Rule 210.e Corrective action date 9/19/19 See attached photo #2</p> <p>Mechanical issue: Rule 605.d Corrective action Date 9/19/19 See attached photo # 5</p> <p>Trash on location: Rule 603.f Corrective action date 9/02/19 See attached photo #4</p> <p>Weeds growing on access road: Rule 603.f Corrective action Date 9/02/19 See attached photo # 1</p> <p>At time of inspection I observed stained soil around WH what appeared to be a leaking 1" valve on flow line. Well Head sign is fading and will need to be replaced. Trash on location by electrical panel. Weeds growing on access road.</p> <p>Weather conditions Sunny and clear Location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>This is a continuing education inspection.</p>	revasr	08/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300016	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913756">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913756</a>