

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

699300017**FIELD INSPECTION FORM**Loc ID 318308 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Burn, Diana		diana.burn@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241086	WELL	PR	03/20/1995	GW	123-08874	SUCKLA-BROWN UNIT 13	PR

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Access Road over grown with weeds see Photo #1		
Corrective Action	Comply with Rule 603.f .	Date:	09/02/2019

Overall Good: ☐**Emergency Contact Number:**Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds overgrown around deadmen and inside of deadmen. see photo #6		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	OTHER		
Comment:	Reporting: per Inspection Doc.# 681900714 2/29/2016 well was TA. Prod.records show well as producing. At time of inspection flow line valves are closed and all prod. equip. has been removed.		
Corrective Action:	Submit reports as per Rule 206.	Date:	09/19/2019
Type	UNUSED EQUIPMENT		
Comment:	Electric control box, cement pumping unit base, electrical panel and breaker box. See pic # 4, #5		
Corrective Action:	Comply with Rule 603.f .	Date:	11/19/2019
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs	Date:	08/21/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical panel		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 241086 Type: WELL API Number: 123-08874 Status: PR Insp. Status: PR**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TACorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 8/19/19 at approximately 12:30 pm, I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #13 KP Kauffman, API # 123-08874 in (WeldCounty) Colorado.</p> <p>While there, I observed a TA well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment on location: Rule 603.f Corrective action date 9/02/2019 See attached photo #4, #5</p> <p>Reporting: Rule 206 Corrective action date 9/19/19</p> <p>Self-reporting: Rule 1002 F(2)D Corrective action Date 9/19/19</p> <p>Weeds growing around Deadmen and inside of Deadmen: Rule 603.f Corrective action date 9/02/19 See attached photo #6</p> <p>Weeds growing on access road: Rule 603.f Corrective action Date 9/02/19 See attached photo # 1</p> <p>At time of inspection I observed Weeds overgrown on access road making it inaccessible, Well is TA since 2/29/2016 per Doc. # 681900714 all production equip. has been removed and prod. Flowline valves are close. Prod. Records show well is producing</p> <p>Weather conditions Sunny and clear Location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>This is a continuing education inspection.</p>	revasr	08/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300018	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913757</a>