

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

699300019**FIELD INSPECTION FORM**
 Loc ID 317660 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239723	WELL	PR	03/20/1995	OW	123-07511	UPRR 42 PAN AM F 1	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:	Weeds growing on access rd. see photo #1		
Corrective Action	Comply with Rule 603.f	Date:	09/02/2019
Overall Good: <input type="checkbox"/>			

Emergency Contact Number:

Comment:	Sign is beginning to fade and will need to be replaced in the near future	Date:	
Corrective Action:			

Good Housekeeping:

Type	DEBRIS		
Comment:	Dead Weeds around Pumping unit base and electric motor.		
Corrective Action:	Compy with Rule 603.f	Date:	09/02/2019
Overall Good: <input type="checkbox"/>			

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239723 Type: WELL API Number: 123-07511 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 8/19/19 at approximately 13:45 pm, I, Inspector Robbie Revas, Conducted an on-site inspection UPRR 42 Pan AM KP Kauffman, API # 123-07511 in (Weld County) Colorado.</p> <p>While there, I observed a Producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris on location: Rule 603.f Corrective action date 9/02/2019 See attached photo #4</p> <p>Weeds growing on access road: Rule 603.f Corrective action Date 9/02/19 See attached photo # 1</p> <p>At time of inspection I observed Weeds overgrown on access road, Debris (Dead Weeds) all around pump jack and electric motor.</p> <p>Weather conditions Sunny and clear Location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>This is a continuing education inspection.</p>	revasr	08/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300020	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913758