

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2019

Submitted Date:

08/19/2019

Document Number:

688305522

FIELD INSPECTION FORM

Loc ID 309599 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16910
Name of Operator: CHURCHILL ENERGY INC
Address: 8177 SOUTH NORFOLK STREET
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Rogers, Tim		tlr19@hotmail.com	
Clark, Kellie	303-987-0241	kmckmc2@aol.com	Designated Agent
Carroll, Kathy	303-987-0241	kc2121@prodigy.net	Designated Agent
Love, Kimbererley J.	(303) 987-0241	kjlkjcar@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218178	WELL	PR	09/12/2013	OW	073-06163	CHAMPLIN-LIMON 2-19	PR

General Comment:

Routine Inspection
Delinquent Form 7s. Stained soil at wellhead.
Pits are closed.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	719-740-0790	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Historic leaking stuffing box (see attached photo). Remove and properly dispose of stained soil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 09/20/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	steel panels		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Vertical Heater Treater	# 2	one not in use?			
Prime Mover	# 1	electric			
Pump Jack	# 1	chemical container			
Deadman # & Marked	# 4				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 218178 Type: WELL API Number: 073-06163 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. Apr 2018 last production data sent to COGCC database.](#)

Corrective Action: [Submit required Form 7\(s\) to COGCC per Rule 309.](#)

Date: 09/20/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402149950	Churchill Energy INC, Champlin-Limon 2-19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913855