

Inspection Photos
Operator: Southland Royalty
Location/API #: 067-09450
Date: 8-14-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Little desirable vegetation within interim reclamation areas.



Photo 3. View of the eastern project area from the northeastern edge facing southward. Cut-slope is not stabilized.



Photo 4. View of sign that is knocked down, and debris around wellhead.