

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/20/2019

Document Number:

688305582

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
309609 _____ Sherman, Susan _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Ray	719-343-5186	rbrown@mulldrilling.com	
Koehler, Bob		bob.koehler@state.co.us	
Akers, Tracy	(719) 767-8805	takers@mulldrilg.com	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267113	WELL	SI	10/24/2017	OG	073-06304	Meteor Unit 2	SI

General Comment:

UIC MIT for repairs, passed
Resubmitted this inspection because Inspection #688305582 had wrong ID number.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	safety		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 719-342-1813

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	steel panels		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 267113 Type: WELL API Number: 073-06304 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: MRRW

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 10/24/2017

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: -22 Csg psi: 0 BH psi: _____

Insp. Status: Pass

Comment: 1.7 BBLs to load the hole by Pro Stim
Casing 0 psi, Tubing -22 prior to test
0 min 360 psi
5 min 360 psi
10 min 350 psi
15 min 350 psi
Casing 0 psi, Tubing -22 after to test
Test Passed, Signed Form 21 is attached
Bradenhead is not plumbed to surface.
Submit Form 5A, if needed, to document repair work.

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in at time of MIT

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305583	Mull Drilling Meteor Unit 2 Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4914600
688305584	Mull Drilling Meteor Unit 2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4914601
688305585	Mull Drilling Meteor Unit 2 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4914602
688305586	Mull Drilling Meteor Unit 2 well sign/safety	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4914603