

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402150719

Date Received:

08/20/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Randy Madison	575-445-6706	rmadison@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901028

Inspection Date: 07/19/2019

FIR Submit Date: 07/19/2019

FIR Status:

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 308004

Location Name: VPR C-634S66W Number: 32SESW County: LAS ANIMAS

Qtrqr: SESW Sec: 32 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.037100 Longitude: -104.806540

FACILITY - API Number: 05-071-00 Facility ID: 260125

Facility Name: VPR C Number: 84

Qtrqr: SESW Sec: 32 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.037100 Longitude: -104.806540

CORRECTIVE ACTIONS:

1 CA# 128358

Corrective Action: Comply with Rule 1003.f.  
Control noxious weeds.

Date: 07/11/2019

Response: CA COMPLETED

Date of Completion: 08/07/2019

Operator Comment: Weeds that could be sprayed from the 24 foot easement that we have with the land owner were sprayed. The soil in the photo and the property owners log cabin has not been disturbed by Wapiti Operating for years.

COGCC Decision:

COGCC  
Representative:

2 CA# 128359

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 08/15/2019

Operator  
Comment:

The road was raised 12" in the hopes of the water running off into the ditch. Rock checks were installed.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Weeds were sprayed where they could be reached from the right of way. Road was built up and numerous rock checks installed to control the erosion.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed:

Title: HSE Specialist

Date: 8/20/2019 2:06:31 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402150728	Photo of Road being built up
402150729	Photo of Road being built up #2
402150730	Photo of Road Built up
402150731	Photo of Rock checks north side of road
402150732	Photo of Rock check south side of road
402150736	Photo iof Rock checks north side of road (middle)
402150737	Photo of Water Chute with Rock checks
402150738	Photo of Rock rip/rap to slow water down
402150739	Photo of Rock Checks northside towards the top
402150740	Photo of Rock Checks on curve.
402150742	Photo of Rock Checks installed.

Total Attach: 11 Files