

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

687905401**FIELD INSPECTION FORM**Loc ID 325197 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87415**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214258	WELL	PR	04/23/1956	GW	067-05592	BONDAD 33-10 10	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report. This inspection does not allievate responsibility for any prior corrective actions not completed.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank lables/placards posted on sign at tank fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted on fence at equipment.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	T-post and hogwire around tank.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 6		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-1" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to dehydrator. 1-2" flowline from dehydrator dump valve to produced water tank. 1-2" flowline from dehydrator to offsite dogleg.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	*DOMESTIC GAS TAP IN SERVICE. 1-1" FLOWLINE FROM WELLHEAD TO DOMESTIC GAS TAP REGULATOR AND VALVE TREE AT EDGE OF LOCATION. ALL VALVES OPEN AND FLOW METER INSTALLED. APPEARS TO BE IN SERVICE AT TIME OF INSPECTION.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	In dehydrator building.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:	(1) on separator stack, (1) on dehydrator stack.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead.		Date:	
Corrective Action:			Date:	
Type: Dehydrator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 214258	Type: WELL	API Number: 067-05592	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Drains	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905409	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915065
687905410	Domestic gas tap.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915066