

# Interim Reclamation and Stormwater Inspection

August 19, 2019

Operator: SUNBURST INC- 83555

Location ID: 417959

Inspection Document #: 697500480

Weld County, CO

SESE Section 36 T11N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 1.** Photo taken of the wellhead. Wellhead appears to be leaking and has not been fixed since the previous inspection. Also, Operator has not properly treated or disposed of the oily waste in accordance with 907.e.; Operator has only put gravel on top of oily waste.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 2.** Photo taken from the pumping unit engine house. Operator has not properly treated or disposed of the oily waste in accordance with 907.e.; Operator has only put gravel on top of oily waste.

Operator did remove the trash inside the pumping unit engine house.

Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 3.** Photo taken from the pumping unit, facing South. Photo illustrates the Operator has controlled weeds.



Inspection Photos

Location Name: Moonshine #36-11-65

Location ID: 417959



**Photo 4.** Photo taken from the north side of the treater shed. Photo illustrates that 2 of the risers have been locked out but not tagged out.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 5.** Photo taken from the north side of the treater shed, facing Northeast. Photo illustrates risers remain at location.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 6.** Photo taken from the north side of the treater shed, facing East. Photo illustrates unused meter run set with no meter.

Inspection Photos

Location Name: Moonshine #36-11-65

Location ID: 417959



**Photo 7.** Photo taken of the heater treater stack. Photo illustrates Operator has failed to install wildlife intrusion mitigation device on top of the heater treater stack.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 8.** Photo taken of the production water tank on location. Operator has installed NFPA label.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 9.** Photo taken from the load line bucket. Photo illustrates stained soil around bucket.



Inspection Photos  
Location Name: Moonshine #36-11-65  
Location ID: 417959



**Photo 10.** Photo taken from the pumping unit engine house. Operator has not removed the unused day barrel.