

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

699300023**FIELD INSPECTION FORM**Loc ID 333132 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241516	WELL	PR	03/01/2019	OW	123-09305	KOSHIO 2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Stained soil near and around Well head and pump jack base

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/20/2019

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Angle iron

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead # 1

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: Electric Motor

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Electric control panel, meter, transformers

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 241516 Type: WELL API Number: 123-09305 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 8/20/19 at approximately 10:00 am, I, Inspector Robbie Revas, Conducted an on-site inspection at the Koshio #2 KP Kauffman, at API # 05-123-09305 in Weld County Colorado.</p> <p>While there, I observed Producing Wellsite</p> <p>During this inspection the following possible compliance issues were observed: Stained soil near and around well head and pump jack base. Rule 907.e 9/20/19 See attached photos #3 and #4</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing education Inspection.</p>	revasr	08/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300024	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915149