

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2019

Submitted Date:

08/20/2019

Document Number:

699300025**FIELD INSPECTION FORM**

Loc ID 318561 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241599	WELL	PR	03/01/2019	OW	123-09388	KIYOTA 2	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue 2" riser fittings appear to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/20/2019
Type	OTHER		
Comment:	Stained soil around 2"riser		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 09/20/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Transformers		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241599 Type: WELL API Number: 123-09388 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: At the time of this inspection the well appears to be shut in all service valves are closed.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 8/20/19 at approximately 11:30 am, I, Inspector Robbie Revas, Conducted an on-site inspection at the Kiyoto 2 KP Kauffman, at API # 05-123-09388 in Weld County Colorado.</p> <p>While there, I observed a Shut in Wellsite</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Housekeeping: Stained soil around 2" flow line riser. Rule 907.e Corrective action date 9/20/19. See attached photo #3.</p> <p>Mechanical Issue: 2" riser fittings appear to be leaking. Rule 605.d Corrective action date 9/20/19. See attached photo #3</p> <p>Reporting: Well report shows that it is a PR well, at time of inspection well appears to be Shut In valves appear to be closed. See attached photos #4, #5, #6</p> <p>Weather is sunny and hot, location is dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education Inspection.</p>	revasr	08/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300026	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915150