

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/12/2019

Submitted Date:

08/14/2019

Document Number:

693900655**FIELD INSPECTION FORM**Loc ID 325801 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email               | Comment                         |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre |       | sabre.beebe@bpx.com | <a href="#">All Inspections</a> |
| ,            |       | SanJuanCOGCC@bp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 215400      | WELL | PR     | 12/20/1989  | GW         | 067-07005 | STATE OF COLORADO<br>AW 2 | RI          |

**General Comment:**[This is an interim reclamation and stormwater inspection.](#)

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 215400 | Type: | WELL | API Number: | 067-07005 | Status: | PR | Insp. Status: | RI |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|  |  |
|--|--|
| Date Final Reclamation Started: _____  | Date Final Reclamation Completed: _____                  |
| Final Land Use: _____  |  |
| Reminder: _____  |  |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>           |  |
| Well plugged _____   | Pit mouse/rat holes, cellars backfilled _____            |
| Debris removed _____   | No disturbance /Location never built _____               |
| Access Roads _____   | Regraded _____   |
| Contoured _____  | Culverts removed _____                                   |
| Gravel removed _____   |  |
| Location and associated production facilities reclaimed _____                              | Locations, facilities, roads, recontoured _____          |
| Compaction alleviation _____   | Dust and erosion control _____                           |
| Non cropland: Revegetated 80% _____  | Cropland: perennial forage _____                         |
| Weeds present _____  | Subsidence _____   |
| 1004.d. FINAL VEGETATION TRANSECT  |  |
| TRANSECT RESULTS OF DISTURBED AREA% _____  |  |
| TRANSECT RESULTS OF REFERENCE AREA% _____  |  |
| TOTAL % OF DESIRABLE VEGETATION COVER _____  |  |
| VEGETATIVE COVER _____   |  |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>           |  |
| Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> |  |
| Date _____   |  |
| Overall Final Reclamation _____  | Well Release on Active Location <input type="checkbox"/> |
| Multi-Well Location <input type="checkbox"/>   |  |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Erosional channeling and scouring is occurring within the northeastern project area.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 08/30/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402144751    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909157</a> |
| 693900656    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909148">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909148</a> |