

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

695101208

FIELD INSPECTION FORM

Loc ID 307653 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89162	WELL	IJ	02/01/2017	DSPW	071-06741	WILD BOAR 21-32 WD	IJ
159046	UIC DISPOSAL	AC	07/19/2000		-	WILD BOAR 21-32 WD	AC
426772	TANK BATTERY	AC	04/14/2009		-	WILD BOAR-633S65W 32NENW	AC

General Comment:

Inspected Facilities

Facility ID: 89162 Type: WELL API Number: 071-06741 Status: IJ Insp. Status: IJ

Facility ID: 159046 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 700

UIC Routine

Inj./Tube: Pressure or inches of Hg -18 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: _____
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: GRAVITY FEED

Test Type: 5 Year Tbg psi: -18 Csg psi: 385 BH psi: 0

Insp. Status: _____

Comment: MONITORED BRADENHEAD AND INJECTION PRESSURE DURING 15 MINUTE MIT. NO FLUXUATION.

Corrective Action: _____ Date: _____

Facility ID: 426772 Type: TANK API Number: - Status: AC Insp. Status: AC

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101209	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915512