

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2019

Submitted Date:

08/21/2019

Document Number:

687905417**FIELD INSPECTION FORM**Loc ID 325962 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 215640 | WELL | PR | 04/01/1989 | GW | 067-07245 | ALBRIGHT-TRIMBLE 1 | PR |

General Comment:[Site inspection and equipment inventory with photos at the end of this report.](#)

LocationOverall Good: ☐

| | | | |
|----------------------|--------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------------------------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Contact information posted on sign. | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Cattle panels around wellhead and pumpjack. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Cattle panels around separator and meter house. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | On separator stack. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 4 | | |
| Comment: | 1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-4" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|---|-------|--|
| Type: Bradenhead | # 1 | | |
| Comment: | PVC bradenhead access. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric VFD drive motor on pumpjack with MCC | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | |
|----------------------|------------|-----------------------|------------|------------------|
| Facility ID: 215640 | Type: WELL | API Number: 067-07245 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing. | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--|
| Compaction | Pass | Culverts | Pass | | | |
| Ditches | Pass | Ditches | Pass | | | |
| Gravel | Pass | | | | | |
| Gradient Terraces | Pass | Gravel | Pass | | | |
| | | | | Material Handling And Spill Prevention | Pass | Spill prevention for chemical injection. |
| Berms | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 687905422 | Location. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916013 |