

McLaughlin 68
API: 05-103-40191
Inspection: 679705137



Photo 1. Well head.

McLaughlin 68
API: 05-103-40191
Inspection: 679705137



Photo 2. Well head with cement to surface & cement string not removed yet.