

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

699300033**FIELD INSPECTION FORM**Loc ID 317693 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239798	WELL	PR	12/01/2017	OW	123-07586	SHELDON SICKLER 2	IO

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds Growing along access road		
Corrective Action:	Comply with Rule 603.f	Date:	09/04/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Starting to fade will need to be replace in the near future		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	New Weeds growing around wellhead.		
Corrective Action:	comply with Rule 603.f	Date:	09/04/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric control panel		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.092180,-140.869530
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 239798 Type: WELL API Number: 123-07586 Status: PR Insp. Status: IO

**Producing Well**

Comment: Reports show well to be producing, at time of inspection Electric control panel appears to be turned off

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

revasr

08/21/2019

On Tuesday 8/21/19 at approximately 10:30am, I, Inspector Robbie Revas, Conducted an on-site inspection at the Sheldon Sickler # 2 KP Kauffman, at

API # 05-123-07586 in Weld County Colorado.

While there, I observed a Producing Wellsite, the well report show the well as producing but the control panel appears to be shut off. See attached photo #4.

During this inspection the following possible compliance issues were observed:

Housekeeping: Weeds growing on lease road and around wellhead Rule 603.f Corrective action date 9/3/19. See attached photo #1, #2, &amp; #3.

Weather is sunny and hot, Location is dry.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Continuing education Inspection.

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300034	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916196">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916196</a>