

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

699300040

**FIELD INSPECTION FORM**

Loc ID 317661 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Pesika, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239724	WELL	PR	12/01/2017	OW	123-07512	SHELDON SICKLER 1	SI

**General Comment:**

Empty text area for general comments.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing Down center of road.		
Corrective Action	Comply with Rule 603.f	Date:	09/04/2019

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign is faded and unlegible needs to be replaced		
Corrective Action:	Comply with Rule 210.e	Date:	09/23/2019

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds growing around Wellsite right of way, dead weeds around pump jack and electrical panel/transformers		
Corrective Action:	Comply with Rule 603.f	Date:	09/04/2019
Type	OTHER		
Comment:	Barbwire fencing/poles lying on ground around pumpjack		
Corrective Action:	Remove debris per Statewide equipment, weeds, waste, and trash requirements according to rule 603 f.		Date: 09/04/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Steel pole around electrical panel, transformer, breaker panel and meter		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	<input type="text"/>		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: <a href="#">Appears to be plumbed to surface</a>			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">Electrical transformers, breaker panel and meter.</a>			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: <a href="#">electric motor</a>			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 239724 Type: WELL API Number: 123-07512 Status: PR Insp. Status: SI**Producing Well**

Comment: Well report shows it to be producing at time of this inspection the well appears to be shut in.

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

On Tuesday 8/21/19 at approximately 13:30 pm, I, Inspector Robbie Revas, Conducted an on-site inspection at the Sheldon Sickler # 1 KP Kauffman, at API # 05-123-07512 in Weld County Colorado.

While there, I observed a Producing Wellsite that at time of inspection appears to be shut in. See attached photos #4 & #5

During this inspection the following possible compliance issues were observed:  
 Housekeeping: Weeds growing down rutted lease access road and around the wellsite ROW, Dead weeds around pump jack and Electrical transformers, breaker panel and meter. Downed barb wire fencing and poles around pump jack. Comply with Rule 603.f Corrective action date 9/4/19. See attached photos #3, #5, #6 and #7

Signs: Wellhead sign is faded and not legible needs to be replace per Rule 210.e See attached photo #2

Corrective action date 9/23/19

Weather is sunny and hot, Location is dry.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Continuing education COGCC Inspection Report Summary Inspection.

revasr

08/21/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300041	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916199">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916199</a>