

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

694900210**FIELD INSPECTION FORM**Loc ID 336028 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287951	WELL	AL	03/14/2018	LO	045-13105	River Ranch C1	AL
288420	WELL	AL	03/14/2018	LO	045-13286	River Ranch C3	AL
288421	WELL	AL	05/20/2014	LO	045-13285	River Ranch C4	AL
288422	WELL	AL	03/14/2018	LO	045-13284	River Ranch C5	AL
288423	WELL	AL	01/02/2014	LO	045-13283	River Ranch C-1H	AL
296974	WELL	PR	10/26/2008	GW	045-16241	RIVER RANCH C9	PR

**General Comment:**

Routine inspection

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock panel		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fence		
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	2 are unmade see photo		
Corrective Action:	mark deadmen	Date:	09/16/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment: Centralized battery						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		
Date:		

**Inspected Facilities**Facility ID: 287951 Type: WELL API Number: 045-13105 Status: AL Insp. Status: ALFacility ID: 288420 Type: WELL API Number: 045-13286 Status: AL Insp. Status: ALFacility ID: 288421 Type: WELL API Number: 045-13285 Status: AL Insp. Status: ALFacility ID: 288422 Type: WELL API Number: 045-13284 Status: AL Insp. Status: ALFacility ID: 288423 Type: WELL API Number: 045-13283 Status: AL Insp. Status: ALFacility ID: 296974 Type: WELL API Number: 045-16241 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 8/14/19 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at URSA River Ranch C Pad, at Location # 336028 in Garfield County, Colorado.</p> <p>While there, I observed Normal production operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Two (2) unmarked dead men.</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	08/15/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402146576	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910953">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910953</a>
694900211	694900210	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910948</a>