

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2019

Submitted Date:

08/22/2019

Document Number:

693700236

FIELD INSPECTION FORM

Loc ID 461838 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10177
Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION
Address: 950 17TH STREET #2200
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Scott Mason		scottmason@enerplus.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450736	WELL	DG	05/07/2019		123-44903	ARKANSAS 8-67-33-4N	EI

General Comment:

COGCC Environmental Staff Inspection as part of complaint request to sample a water well of area resident. Location is being prepped for flowback and production. Site equipment still under construction. Pipeline construction ongoing adjacent to pad. This inspection focuses only on spill ID 466609 reported by Operator and recently resolved.

Inspected Facilities

Facility ID: 450736 Type: WELL API Number: 123-44903 Status: DG Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: 03689960 Owner Name: Valenica(Bringleson) GPS : 40.611400 -104.893110
 Lat _____ Long _____

Field Parameters:

Sample Location: Other Comment: Outdoor hydrant

Sample		Sample Type: <u>GROUND WATER</u>	
Time: <u>08/21/2019 1:45</u>	(MM/dd/yyyy hh:mm)	GPS: Lat _____	Long _____
BTEX: <u>YES</u>	TPH: <u>YES</u>	Anion: <u>YES</u>	Captions: <u>YES</u> General Chemistry: <u>YES</u>
Dissolved Methane: <u>YES</u>	Composition: _____	Stable Isotopes: <u>YES</u>	8260: <u>YES</u>
8270: <u>YES</u>	RCRA Metals: <u>NO</u>	910-Metals: <u>YES</u>	PAH: <u>YES</u>
Other: _____			
Comment: See COGCC Sample Facility 762100 for more information			

Lab:

Lab Name _____
 ALS Fort Collins _____

Spill/Remediation:

Comment: [Operator reported a spill from the check ball assembly that occurred 8/3/2019. Spill was confined to the cellar. COGCC did not observed impacts around the wellhead related to a spill. Spill was assigned ID 466609 and has been resolved.](#)
 Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700237	Arkansas Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916371