

Inspection Photos  
Operator: BP America  
Location/API #: 067-08216  
Date: 8-19-2019



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of southern fill slope facing westward. Revegetation is sparse/young, but appears to be progressing. Some hydromulch remains on soil surface.





Photo 3. View of wattle in the southern project area that is no longer functioning. This is not an appropriate BMP for this area.





Photo 4. View of musk thistles within the southwestern project area.





Photo 5. View of reference area vegetation facing southward.