

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

08/22/2019

Document Number:

689802936

FIELD INSPECTION FORM

Loc ID 312758 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 82440
Name of Operator: STEHLE OIL COMPANY
Address: P O BOX 1577
City: CRAIG State: CO Zip: 81626

Findings:

- 13 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Stehle, Cary	(970) 824-6909	carystehle@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222189	WELL	SI	11/01/2018	OW	081-05136	ILES INVESTMENT CO 1-23	SI

General Comment:

COGCC Inspection Report 689802936 Summary
On Monday 07/15/2019 at approximately 11:15, I, Inspector Emily Waldron, conducted a field inspection at Stehle Oil Company Iles Investment Co 1-23, at 05-081-05136 in Moffat County Colorado. While there, I performed a follow up inspection to inspection report 689801290. No corrective actions from that report have been performed.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate on tanks or containers.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/03/2014
Type	BATTERY		
Comment:	At entrance.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/03/2014

Emergency Contact Number:			
Comment:	970-824-6909		Date:
Corrective Action:			

Good Housekeeping:			
Type	WEEDS		
Comment:	Noxious and annual weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/06/2018
Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. 1 unused 3" steel riser observed in pit not marked for abandonment or locked out tagged out. 3 unused 3" steel risers observed at tan tank cluster (40.31086, -107.67829) not marked for abandonment or locked out tagged out. 1 unused 2" steel riser observed at tan tank cluster not marked for abandonment or locked out tagged out. 1 unused 3" steel riser observed at white tank (40.31084, -107.67812) not marked for abandonment or locked out tagged out. 2 unused 3" steel risers and 1 unused 2" steel riser observed at entrance (40.31051, -107.67846) not marked for abandonment or locked out tagged out.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/11/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: All spills and releases mentioned in previous inspections remain unresolved. Operator has not contacted COGCC EPS.

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1				,

Comment: **Stained soil and leaks observed at tank base.**

Corrective Action: **Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.**

Date: **07/21/2016**

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: **Inadequate berms around tank(s).**

Corrective Action: **Repair or install berms or other secondary containment devices per Rule 605.a.(4).**

Date: **07/21/2016**

Contents	#	Capacity	Type	Tank ID	SE GPS
	3		STEEL AST		,

Comment:

Corrective Action:

Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: **Inadequate berms around tank(s).**

Corrective Action: **Repair or install berms or other secondary containment devices per Rule 605.a.(4).**

Date: **07/21/2016**

Venting:

Yes/No	
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 222189 Type: WELL API Number: 081-05136 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Netting or fencing not maintained, gaps exist around perimeter.

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: Netting or fencing not maintained, gaps exist around perimeter.

Corrective Action

Net or fence pit to prevent access per rule 902.d.

Date: 07/03/2018

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: NO

Comment: Oil on pit, less than 2 feet of freeboard, no permit on file.

Corrective Action

Lower fluid level so at least two feet of freeboard exists per Rule 902.b.
Remove oil from pit per Rule 902.c.
Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 06/22/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689803003	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916770