

MARALEX RESOURCES, INC.– 53255
API# 05-045-06376 ALBERTSON #15-1
Inspection Date : 8/20/2019



Location overview looking W.



Wellhead with fence and sign

MARALEX RESOURCES, INC.– 53255
API# 05-045-06376 ALBERTSON #15-1
Inspection Date : 8/20/2019



Separator and meter



Flowline riser disconnected.
Disconnected flowline risers not LOTO.

MARALEX RESOURCES, INC.– 53255
API# 05-045-06376 ALBERTSON #15-1
Inspection Date : 8/20/2019



Flowline riser with fence



**Blowdown tank with fence and netting.
Flowline risers with pipe fencing in background.**

MARALEX RESOURCES, INC.– 53255
API# 05-045-06376 ALBERTSON #15-1
Inspection Date : 8/20/2019



Blowdown pit with fence and netting.
No weed control inside fence. Holes in netting.