

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402152564

Date Received:

08/22/2019

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

720-644-6997

awenk@bisonog.com

Ariana Solis

720-644-6997

asolis@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200568

Inspection Date: 08/08/2019

FIR Submit Date: 08/09/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455519

Location Name: Boomslang Fed 8-60 Number: 14B County: _____

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

FACILITY - API Number: 05-123- -00 Facility ID: 455519

Facility Name: Boomslang Fed 8-60 Number: 14B

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

CORRECTIVE ACTIONS:

1 CA# 129086

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator
Comment:

Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC Decision "Not Approved"

Based on the photos provided, BMPs do not appear to have been installed in accordance with good engineering practices. Photos also appear to pre-exist the 8/16/2019 inspection; documentation missing a date stamp.

Additionally, perimeter stormwater controls are required to be installed in accordance with good engineering practices early in the location construction process (before site grading) so BMPs can function throughout construction. The stage of the construction is moot.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

2  CA# 129087

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator
Comment:

Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC Decision "Not Approved"

Based on the photos provided, BMPs do not appear to have been installed in accordance with good engineering practices. Photos also appear to pre-exist the 8/16/2019 inspection; documentation missing a date stamp.

Additionally, perimeter stormwater controls are required to be installed in accordance with good engineering practices early in the location construction process (before site grading) so BMPs can function throughout construction. The stage of the construction is moot.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

3  CA# 129088

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator
Comment:

Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC Decision "Not Approved"

Based on the photos provided, BMPs do not appear to have been installed in accordance with good engineering practices. Photos also appear to pre-exist the 8/16/2019 inspection; documentation missing a date stamp.

Additionally, perimeter stormwater controls are required to be installed in accordance with good engineering practices early in the location construction process (before site grading) so BMPs can function throughout construction. The stage of the construction is moot.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

4  CA# 129089

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Please see attached photos. Pad was still undergoing initial construction at the time of inspection.

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC Decision "Not Approved"

Based on the photos provided, BMPs do not appear to have been installed in accordance with good engineering practices. Photos also appear to pre-exist the 8/16/2019 inspection; documentation missing a date stamp.

Additionally, perimeter stormwater controls are required to be installed in accordance with good engineering practices early in the location construction process (before site grading) so BMPs can function throughout construction. The stage of the construction is moot.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed:

Title: Regulatory Analyst

Date: 8/22/2019 11:29:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402152564	FIR RESOLUTION SUBMITTED
402152592	Corrective Action Photos

Total Attach: 2 Files