

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2019

Submitted Date:

08/22/2019

Document Number:

693200391**FIELD INSPECTION FORM**
 Loc ID 335635 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Elsener, Caerus		COGCC.inspections@caerusoilandgas.com	<a href="#">All Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466606	SPILL OR RELEASE	AC	08/09/2019		-	L19-595 Dumpline	EG

**General Comment:**[Engineering Integrity Inspection performed on August 20, 2019. In response to initial form 19 spill report Doc # 402137160](#)[Corrective actions noted in inspection 698100059, that have not been addressed are still applicable](#)

**Inspected Facilities**

Facility ID: 466606 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines	
----	-----------------	------------	--

Flowline DescriptionFlowline Type: Dump LineSize: 2"Material: Carbon SteelVariance: NoAge: 1-5 YrsContents: Produced WaterIntegrity SummaryFailures: Internal CorrosionSpills: YesRepairs Made: YesCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: No

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: Submit a flowline pressure test that was performed before returning flowline back into service via Form 4 and email to inspector

Corrective Action:

Date: 08/30/2019**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200392	Flowline Repairs made	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917011">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917011</a>