

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2019

Submitted Date:

08/22/2019

Document Number:

694900247

FIELD INSPECTION FORM

Loc ID 334069 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262866	WELL	PR	09/17/2002	GW	045-08064	SHIDLER 1-7 (G1)	PR
268506	WELL	PR	07/08/2004	GW	045-09268	HMU 1-6D (G1)	PR
282079	WELL	PR	08/25/2006	GW	045-11633	SHIDLER FEDERAL 1-9 (G1SW)	PR
282080	WELL	PR	08/26/2006	GW	045-11632	SHIDLER FEDERAL 1-2C (G1SW)	PR
282081	WELL	PR	07/21/2006	GW	045-11631	SHIDLER 1-1C (G1SW)	PR

General Comment:

routine inspection

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type TANK BATTERY

Comment: livestock fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Vertical Heated Separator # 3

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 5

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment: centralized containment 24 Bbls					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	centralized containment				
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>262866</u>	Type:	<u>WELL</u>	API Number:	<u>045-08064</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>268506</u>	Type:	<u>WELL</u>	API Number:	<u>045-09268</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282079</u>	Type:	<u>WELL</u>	API Number:	<u>045-11633</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282080</u>	Type:	<u>WELL</u>	API Number:	<u>045-11632</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282081</u>	Type:	<u>WELL</u>	API Number:	<u>045-11631</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
Retention Ponds						
Ditches		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/22/19 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus Shideler G1SW, at Location # 334069 in Garfield County, Colorado. While there, I observed Normal production operations.. This is a summary of inspection report.</p>	ramseys	08/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900258	694900247	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917211