

Inspection Photos
Operator: BP America
Location/API #: 067-08898
Date: 8-21-2019



Photo 1. View of wattles out of place, full of sediment, and erosion occurring at the well pad entrance.



Photo 2. View of failed wattle, sedimentation, and erosion within the southeastern project area.



Photo 3. View of hydromulch, sparse revegetation, and wattle on well pad cut-slope.



Photo 4. Birdseye view of revegetation on the well pad cut-slope, which remains sparse and grazed. Livestock exclusion appears needed.



Photo 5. View of the western fill slope from the northwestern edge facing southward. Well pad berm is in place.



Photo 6 View of reference area vegetation facing southward.