

Inspection Photos
Location Name: Carl A Miller A #2
Location ID: 317739



Photo #1 Weeds growing on lease access road.



Photo #2 Wellhead sign beginning to fade



Inspection Photos
Location Name: Carl A Miller A #2
Location ID: 317739



Photo # 3 Wellhead/Pump jack Weeds growing around wellsite ROW.



Photo #4 Weeds growing behind Electric control pane and transformer.

Inspection Photos
Location Name: Carl A Miller A #2
Location ID: 317739



Photo # 5 Weeds growing around wellsite ROW wellsite ROW.