

McLaughlin 67  
API: 05-103-40196  
Inspection: 679705178



Photo 1. Shale rock loading of bore hole.



Photo 2. Top of cement.