

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/22/2019

Document Number:

679705170

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Moran, Rick On-Site Inspection   
315205 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
, Argali Exploration Company		chloenorman@hotmail.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Rector, Jeff		jbrduco@yahoo.com	
Rector, Brian		brector1983@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230411	WELL	SI	06/01/2019	GW	103-08074	FEDERAL 1-32	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 8-20-2019 at approximately 13:15, inspector Rick Moran, conducted a follow up inspection at Argali Exploration Company well Federal 1-32 in Rio Blanco county of FIR document 679703128 and 679704675.

The following compliance issues were observed as uncompleted:

- 1) Unused tanks. Photo 2 & 4. Complete by 5-30-2019.
- 2) Weeds in pit. Photo 3 & 5. Complete by 3-12-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705170.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Two unused ~10 bbl tanks on location. Unclear if tanks are intended to replace pits.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/30/2019
Type	WEEDS		
Comment:	Weeds & vegetation in pits.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/12/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230411 Type: WELL API Number: 103-08074 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 39.827000                      Long: -108.644200

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

Lining:

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: Well head pit.

Corrective Action  Date: \_\_\_\_\_

Fencing:

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action  Date: \_\_\_\_\_

Netting:

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action  Date: \_\_\_\_\_

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 39.826800                      Long: -108.644800

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

Lining:

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: Gas meter pit.

Corrective Action  Date: \_\_\_\_\_

Fencing:

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action  Date: \_\_\_\_\_

Netting:

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705171	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917295</a>