

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2019

Submitted Date:

08/22/2019

Document Number:

679705178

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
398964 _____ Moran, Rick _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 27900

Name of Operator: EQUITY OIL CO

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199946	WELL	AL	11/11/1911	LO	103-40196	MCLAUGHLIN 67	PA

General Comment:

[COGCC Inspection Report Summary.](#)

On 8-13-2019, inspector Rick Moran, was on location for the plugging of Whitening well McLaughlin 67 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679705178.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 199946 Type: WELL API Number: 103-40196 Status: AL Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Diamond Back

Contractor Phone: 435-789-8238

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4 - 150

Cement Volume (sx): 67

Good Return During Job: _____

Cement Type: Portland Tipe I/II

Comment: Hole filled with shale rock and top with sand to a depth of 150 feet. Followed by cement plug that flowed to surface, then fell back 3 ft after the cement tubing string was removed.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705179	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917299