

Inspection Photos
Location Name: LILLI UNIT-68N58W /9NESE
Location #: 327156



Photo #1
Lilli Unit 9-9 (05-123-14237) UIC - Injection Wellsite
UIC Annual Inspection
Not Injecting – Gas / Injection line: Shut
Shut-In | SI



Photo #2
Lilli Unit 9-9 UIC - Injection Wellsite
Well sign

Inspection Photos
Location Name: LILLI UNIT-68N58W /9NE5E
Location #: 327156




Photo #3
Lilli Unit 9-9 UIC - Injection Wellsite
Shut-In | SI
Tbg. Press: 260#



Photo #4
Lilli Unit 9-9 UIC - Injection Wellsite
Shut-In | SI
Csg. Press: 20#

Inspection Photos
Location Name: LILLI UNIT-68N58W /9NE5E
Location #: 327156



Colorado Oil & Gas Conservation Commission
40.67418, -103.86025, 1403.0m, 343°
08/22/2019 11:55:26 AM

Photo #5

Lilli Unit 9-9 UIC - Injection Wellsite

Shut-In | SI

Bradenhead Press: (-1#)



Colorado Oil & Gas Conservation Commission
40.68406, -103.87557, 1419.0m, 143°
08/21/2019 03:46:39 PM

Photo #6

Lilli Unit Gas Plant | UIC - Injection Facility

Facility Sign | Entrance

recent insp.

Inspection Photos
Location Name: LILLI UNIT-68N58W /9NE5E
Location #: 327156



Colorado Oil & Gas Conservation Commission
40.68393, -103.87695, 1410.0m, 49°
08/21/2019 03:45:38 PM



Colorado Oil & Gas Conservation Commission
40.68431, -103.87451, 1433.0m, 79°
08/21/2019 03:21:25 PM

Photo #7

Lilli Unit Gas Plant | UIC - Injection Facility

Facility view

recent insp.

Photo #8

Lilli Unit Gas Plant | UIC - Injection Facility

Gas Injection Compressor | Discharge line

recent insp.

Inspection Photos
Location Name: LILLI UNIT-68N58W /9NESE
Location #: 327156



Photo #9

Lilli Unit Gas Plant | UIC - Injection Facility

Gas Injection discharge line header

recent insp.



Photo #10

Lilli Unit Gas Plant | UIC - Injection Facility

Gas Injection discharge line header

Final stage to UIC wells.

recent insp.