

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign faded becoming not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/19/2019

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	"Properly treat or dispose of oily waste in accordance with 907.e."	Date:	09/19/2019
Type	OTHER		
Comment:	Mechanical issue, 1" valve on tubing flowline appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/19/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Ancillary equipment		# 1		
Comment:	electrical panel			
Corrective Action:				Date:
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:				Date:
Bradenhead		# 1		
Comment:	apperars to be plumbed to surface			
Corrective Action:				Date:
Pump Jack		# 1		
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/19/19 at approximately 10:00 am, I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #1 KP Kauffman, API # 123-07480 in (WeldCounty) Colorado. While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Stained soil: Rule 907.e Corrective action date 9/19/2019 See attached photo # 3 Sign faded: Rule 210.e Corrective action date 9/19/19 See attached photo #1 Mechanical issue: Rule 605.d Corrective action Date 9/19/19 See attached photo # 3</p> <p>At time of inspection I observed stained soil around WH what appeared to be a leaking 1" valve on flow line. Well Head sign is fading and will need to be replaced. Weather conditions Sunny and clear Location is dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. This is a continuing education inspection.</p>	revasr	08/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402149839	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913761
699300014	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913755