

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2019

Submitted Date:

08/19/2019

Document Number:

699300015

FIELD INSPECTION FORM

Loc ID 318307 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241085	WELL	PR	09/08/1976	OW	123-08873	SUCKLA-BROWN UNIT 12	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Weeds growing on access road see photo #1		
Corrective Action	Comply with Rule 603.f .	Date:	09/02/2019

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign fading and becoming unlegible see photo #2		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/19/2019

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around WH see photo #5		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e."	Date:	09/19/2019
Type	TRASH		
Comment:	Trash on location by electric panel see photo #4		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	OTHER		
Comment:	Mechanical issue 1" valve on tubind appears to be leaking		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e."	Date:	09/19/2019

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	PUMP JACK		
Comment:	steel tubing		
Corrective Action:		Date:	

Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: appears to be plumbed to surface			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: electric motor			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: electrical panel			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241085 Type: WELL API Number: 123-08873 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/19/19 at approximately 11:30 am, I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #12 KP Kauffman, API # 123-08873 in (WeldCounty) Colorado. While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Stained soil: Rule 907.e Corrective action date 9/19/2019 See attached photo # 5 Sign faded: Rule 210.e Corrective action date 9/19/19 See attached photo #2 Mechanical issue: Rule 605.d Corrective action Date 9/19/19 See attached photo # 5 Trash on location: Rule 603.f Corrective action date 9/02/19 See attached photo #4 Weeds growing on access road: Rule 603.f Corrective action Date 9/02/19 See attached photo # 1 At time of inspection I observed stained soil around WH what appeared to be a leaking 1" valve on flow line. Well Head sign is fading and will need to be replaced. Trash on location by electrical panel. Weeds growing on access road. Weather conditions Sunny and clear Location is dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. This is a continuing education inspection.</p>	revasr	08/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402149840	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913762
699300016	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913756