



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing on access rd. see photo #1		
Corrective Action:	Comply with Rule 603.f	Date:	09/02/2019

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	Sign is beginning to fade and will need to be replaced in the near future		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Dead Weeds around Pumping unit base and electric motor.		
Corrective Action:	Compy with Rule 603.f	Date:	09/02/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239723 Type: WELL API Number: 123-07511 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 8/19/19 at approximately 13:45 pm, I, Inspector Robbie Revas,                      Conducted an on-site inspection UPRR 42 Pan AM KP Kauffman, API # 123-07511 in                      (Weld County) Colorado.                      While there, I observed a Producing well site.                      During this inspection the following possible compliance issues were observed:                      Debris on location: Rule 603.f Corrective action date 9/02/2019 See attached photo #4                      Weeds growing on access road: Rule 603.f Corrective action Date 9/02/19 See attached                      photo # 1                      At time of inspection I observed Weeds overgrown on access road, Debris ( Dead Weeds)                      all around pump jack and electric motor.                      Weather conditions Sunny and clear Location is dry                      A follow up on this site inspection needs to be conducted to ensure the                      compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      This is a continuing education inspection.</p>	revasr	08/19/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402149843	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913764">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913764</a>
699300020	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913758">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4913758</a>