

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402151482  
Date Received:  
08/21/2019

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10691  
Name of Operator: PHOENIX RESOURCES LLC  
Address: 5566 S SYCAMORE STREET  
City: LITTLETON State: CO Zip: 80120  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Taylor Heffner	281-460-1517	theffner@phxresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 697000053  
Inspection Date: 08/20/2019 FIR Submit Date: 08/21/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC Company Number: 10691  
Address: 5566 S SYCAMORE STREET  
City: LITTLETON State: CO Zip: 80120

### LOCATION - Location ID: 414589

Location Name: MOSHER Number: 1-1H County: LINCOLN  
Qtrqtr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6  
Latitude: 38.938370 Longitude: -103.388340

### FACILITY - API Number: 05-073-00 Facility ID: 414591

Facility Name: MOSHER Number: 1-1H  
Qtrqtr: SESE Sec: 1 Twp: 13S Range: 54W Meridian: 6  
Latitude: 38.938370 Longitude: -103.388340

### CORRECTIVE ACTIONS:

1 ☒ CA# 129468

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/21/2019

Response: CA COMPLETED Date of Completion: 08/16/2019

Operator Comment: Stuffing box rubbers were the cause of the leak of oil onto the wellhead. On Friday, August 16th, our lease operator replaced these rubbers and cleaned up the soil near the wellhead. Stuffing box rubbers can be variable in how long they will function before requiring replacement. We plan on replacing these on a quarterly basis going forward - if we find that this time is too long, we will adjust accordingly.

COGCC Decision: Approved

COGCC Representative: Operator replaced stuffing box rubbers and cleaned wellhead.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Attached picture was taken on August 16th after stuffing box rubbers were replaced.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: \_\_\_\_\_

Title: Partner

Date: 8/21/2019 10:52:58 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402151482	FIR RESOLUTION SUBMITTED
402151488	Wellhead Photo

Total Attach: 2 Files