

# Interim Reclamation and Stormwater Inspection

August 21, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 452820

Inspection Document #: 697500515

Weld County, CO

NWNW Section 33 T3N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates the Operator has performed Interim Reclamation activities to reduce areas only needed for production operations.



**Photo 2.** Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 3.** Photo taken from the well location, facing East.  
See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing North.  
See comments under Photo 1.

Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 5.** Photo taken from the well location, facing Northwest. Photo illustrates an area of pooled irrigation water. This pooling indicates Interim areas have not been properly contoured.



Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 6.** Photo taken from a section of the northern flowline, facing North. Photo illustrates an area of the flowline that has been planted with a grass mix. Alfalfa will be planted in the Spring of 2020.

Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 7.** Photo taken from a section of the central flowline, facing North.  
Photo illustrates a significant bare patch with no vegetative growth.



Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 8.** Photo taken from the previous central flowline area, facing South.  
See comments under Photo 7.

Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 9.** Photo taken from a section of the southern flowline, facing North. Photo illustrates an area of the flowline that has been planted in corn. Corn establishment was minimal with the primary growth of barnyard grass.



Inspection Photos  
Location Name: HERGENREDER /22N2-4HZ  
Location ID: 452820



**Photo 10.** Photo taken from a section of the southern flowline, facing East.  
See comments under Photo 9.