

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2019

Submitted Date:

08/26/2019

Document Number:

692401273

**FIELD INSPECTION FORM**

Loc ID 463987 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**  
OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Contact Information:**

Contact Name	Phone	Email	Comment
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com	
		sandridgeenvironmental@sandridgeenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463988	WELL	XX	04/16/2019		057-06623	PRU Alcorn 0880 1-10	CI

**General Comment:**

This is an Follow Up to Construction Insp Doc#692401182, Dated 7/18/19. Corrective Actions at site have been resolved.  
NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 7/8/18. Conditions at time of Inspection were Clear Sunny Skies, at 75 degrees F with steady wind from the South. Elevation at Site is 8120 ft.

**Location Construction**

Location ID: 463987 CDP: \_\_\_\_\_  
Comment: Construction appears complete at Location. Salvaged topsoil has wattles installed as perimeter BMP.  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: This Location is within a Sensitive Wildlife Habitat; Greater Sage Grouse and CPW Black Bear area.  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					
DITCHES	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					
SILT FENCES	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					
BERMS	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					
RETENTION PONDS	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					
SLOPE ROUGHENING	Yes				
Comments: Erosion BMPs: <input style="width:90%;" type="text"/>					
Other BMPs: <input style="width:90%;" type="text"/>					
Corrective Action: _____ Date: _____					

**Comment:** BMPs have been repaired and rocking of roads and culverts completed as well as additional BMPs installed.

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 463988 Type: WELL API Number: 057-06623 Status: XX Insp. Status: CI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401274	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919858">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919858</a>