

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/14/2019

Submitted Date:

08/26/2019

Document Number:

692401275

FIELD INSPECTION FORM
 Loc ID 458558 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458558	LOCATION	AC	10/31/2018		-	Marmot 0880 S19 CTB	CI

General Comment:

This is an Follow Up to Construction Insp Doc#692401181, Dated 7/18/19. Corrective Actions at site have been resolved.

Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 7/15/18. Conditions at time of Inspection were Clear Sunny Skies, at 78 degrees F with steady wind from the South. Elevation at Site is 8100 ft.

Location Construction

Location ID: 458558 CDP:

Comment: Construction remains in Process. Site size has been reduced. Geo-Tex fabric was being installed on Pad area at time of inspection. Topsoil is now Salvaged at South end of Location.

Corrective Action: Date:

Form 2A COAs:

Comment:

Corrective Action: Date:

Wildlife BMPs:

Comment: This Location is within a Sensitive Wildlife Habitat; Greater Sage Grouse and CPW Black Bear area.

Corrective Action: Date:

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

SILT FENCES	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

SLOPE ROUGHENING	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

BERMS	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 458558 Type: LOCATION API Number: - Status: AC Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401276	Inspection Photos CI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919859