

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2019

Submitted Date:

08/26/2019

Document Number:

693501181**FIELD INSPECTION FORM**Loc ID 333124 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|---------------------------|---------------------------------|
| Gomez, Jason | | jason.gomez@state.co.us | |
| Lara-Mesa, Susana | 303-825-4822 | cogcc@kpk.com | All inspections |
| Medina, Justin | | justin.medina@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 240925 | WELL | PR | 06/01/2018 | OW | 123-08713 | NESSSU-KINDER 16 | PR |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|---|--|------------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Reporting: PU equipment has been remove from well head and is disassembled on ground. PU has been disassembled and laying on ground since 10-19-17 per FIR DOC#678301121. | | |
| Corrective Action: | Submit reports as per Rule 206. | | Date: 07/24/2019 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | PU, walking beam, samson post, and Misc. PU parts. PU has been disassembled and laying on ground since 10-19-17 per FIR DOC#'s 678301121 and 693500494. | | |
| Corrective Action: | Comply with rule 603 f | | Date: 07/24/2019 |

Overall Good: ☐

| | | | | |
|--|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | |
|--------------------|---------------|--|-------|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Cattle panels | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|--------------------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | PU disassembled and laying on ground | | |

| | | | |
|------------------------|----|-------|--|
| Corrective Action: | | Date: | |
| <u>Venting:</u> | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| <u>Flaring:</u> | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 240925 Type: WELL API Number: 123-08713 Status: PR Insp. Status: PR**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday August 26 2019 at approximately 3:23 PM, I, Inspector Randy Silver, conducted an on-site inspection at a KP Kauffman site Nesssu-Kinder #16, at API# 05-123-08713 in Weld County Colorado.</p> <p>While there, I observed Production well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment: Rule 603 f Corrective action date of 7-24-19 See photos 1,2,3</p> <p>Reporting: Rule 206 Corrective action date of 7-24-19</p> <p>This is a follow up inspection to Doc# 693500494 at time of inspection Well head sign had new sticker installed. Unused equipment and reporting issues appear to not have been addressed at time of inspection. PU has been dismantled since 10-19-17 per FIR Doc# 678301121.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | silverr | 08/26/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693501182 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4919938 |