

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2019

Submitted Date:

08/26/2019

Document Number:

679601415**FIELD INSPECTION FORM**Loc ID 330030 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
, Engineering		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250429	WELL	SI	02/01/2019	GW	123-18232	CAVANAGH 36-10H6	WO
447032	TANK BATTERY	AC	07/29/2016		-	CAVANAGH-65N66W 36NWSE	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter house is on location. See attached photo		
Corrective Action:	Comply with Rule 603.f.	Date:	11/26/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Panel fencing surrounding gas meter house.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250429 Type: WELL API Number: 123-18232 Status: SI Insp. Status: WO

Producing Well

Comment:

Corrective Action:

Date:

Idle WellPurpose: ☒ Shut In☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment:

FORM 42 DOC#: 402132842 is in well file. Awaiting completion of PA well and a FORM 6(s) to be filed.

Corrective Action:

Date:

Facility ID: 447032 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment:

All equipment has been removed from tank battery EXCEPT gas meter house. See attached photo .

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Monday, August 26, 2019 at approximately 14:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at CAVANAGH 36-10H6 (Noble Energy), at API #: 05-123-18232 in WELD COUNTY Colorado.

While there, I observed a cut and capped wellhead.

During this inspection the following possible compliance issues were observed:

1. Unused gas meter house still on location. All other production equipment has been removed from tank battery. COMPLY WITH RULE 603.F. (Corrective Action Date: November 26, 2019) See attached photo #3.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

santistb

08/26/2019

Continuing Education Inspection

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
679601416	Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4920137